

NCHRP 9-63 Field Update

ETF Meeting

May 30, 2024



The following slides were not developed using artificial intelligence (AI)



End MP 106th St. NW Emulsion Source WcAsphalt-Regina Width, ft. 29 Emulsion Type CQS-1HP # of Lanes 2 Aggregate Source Lane Width, ft. 12 Aggregate Type Gravel Shoulder Width, ft. 2.5 Aggregate Size, in. Type 3 AADT < 750 50 Application Rates Posted Speed, mph 55 Target Actual Standard Mix design method 1st Micro, Ib/sy 25 20.0 2nd Micro/ Ib/sy	DDO IECT INIEO					
Length, miles 3						
Start MP						•
End MP 106th St. NW Emulsion Source McAsphalt-Regina Width, ft. 29 Emulsion Type CQS-1HP # of Lanes 2 Aggregate Source Lane Width, ft. 12 Aggregate Type Gravel Shoulder Width, ft. 2.5 Aggregate Size, in. Type 3 AADT < 750 50 Application Rates Posted Speed, mph 55 Target Actual Mix design method 1st Micro, Ib/sy 25 20.0 2nd Micro/ Ib/sy 25 20.0		_		Application	Microsu	ırfacing
Width, ft. 29 Emulsion Type CQS-1HP # of Lanes 2 Aggregate Source Strata Lane Width, ft. 12 Aggregate Type Gravel Shoulder Width, ft. 2.5 Aggregate Size, in. Type 3 AADT < 750	Start MP	SR 5		Contractor	AST	ECH
# of Lanes 2 Aggregate Source Strata Lane Width, ft. 12 Aggregate Type Gravel Shoulder Width, ft. 2.5 Aggregate Size, in. Type 3 AADT <	End MP	106th St. NW		Emulsion Source	McAspha	lt-Regina
Lane Width, ft. Shoulder Width, ft. Shoulder Width, ft. ABADT AADT AFFICIAL STATE SECTION Start MP Lane Direction Canopy Open-sunny ABADT ABADT ABADT ABADT ARADT AFFICIAL STATE SECTION Start MP Lane Direction Canopy Open-sunny ABADT ABADT ABADT ABADT ABADT AFFICIAL STATE SECTION Start MP Lane Direction ABADT	Width, ft.			Emulsion Type	CQS-	-1HP
Shoulder Width, ft. 2.5 Aggregate Size, in. Type 3 AADT < <750	# of Lanes	2		Aggregate Source	Str	ata
AADT <	Lane Width, ft.	12		Aggregate Type	Gra	ıvel
Posted Speed, mph 55	Shoulder Width, ft.	2.5		Aggregate Size, in.	Тур	e 3
Mix design method 1st Micro, lb/sy 25 20.0	AADT	<750		50	Applicati	on Rates
TEST SECTION Start MP 1278 from RR 1st Date Placed 8/27/20 Time Placed 8:45AM End MP 1278+500 Air Temperature at Placement, F 54.0 Lane Direction SB Pavement Surface Temperature, F 71.0 Canopy Open-sunny Relative Humidity, % 84.0 2nd Date Placed n/a Time Placed n/a Air Temperature at Placement, F n/a Pavement Surface Temperature, F n/a Relative Humidity, % n/a Layout Straight and Flat Existing surface type Micro/slurry Existing Primary Distress Weathering Existing Secondary Distress None Existing Surface Clean? Yes Existing After Placement 2021 2022 Average rut depth, in. 0.029 0.208 0.211 Sand patch results, avg. diam., in. 19.30 9.67 11.78 12.50	Posted Speed, mph	55			Target	Actual
TEST SECTION Start MP 1278 from RR 1st Date Placed 8/27/20 Time Placed 8:45AM End MP 1278+500 Air Temperature at Placement, F 54.0 Lane Direction SB Pavement Surface Temperature, F 71.0 Canopy Open-sunny Relative Humidity, % 2nd Date Placed Air Temperature at Placement, F n/a Air Temperature at Placement, F n/a Pavement Surface Temperature, F n/a Relative Humidity, % 1 n/a Relative Humidity, % Layout Straight and Flat Existing surface type Existing Primary Distress Existing Secondary Distress Existing Surface Clean? Yes Existing After Placement 2021 2022 Average rut depth, in. 0.029 0.208 0.211 Sand patch results, avg. diam., in.	Mix design method			1st Micro, lb/sy	25	20.0
Start MP				2nd Micro/ lb/sy		
Start MP						
End MP 1278+500 Air Temperature at Placement, F 54.0 Lane Direction SB Pavement Surface Temperature, F 71.0 Canopy Open-sunny Relative Humidity, % 84.0 2nd Date Placed n/a Time Placed n/a Air Temperature at Placement, F n/a Pavement Surface Temperature, F n/a Relative Humidity, % n/a Layout Straight and Flat Existing surface type Micro/slurry Existing Primary Distress Weathering Existing Secondary Distress Existing Surface Clean? Yes Existing After Placement 2021 2022 Average rut depth, in. 0.029 0.208 0.211 Sand patch results, avg. diam., in. 19.30 9.67 11.78 12.50	TEST SECTION					
Lane Direction SB Pavement Surface Temperature, F 71.0 Canopy Open-sunny Relative Humidity, % 84.0 2nd Date Placed n/a Time Placed n/a Air Temperature at Placement, F n/a Pavement Surface Temperature, F n/a Relative Humidity, % n/a Layout Straight and Flat Existing surface type Micro/slurry Existing Primary Distress Weathering Existing Secondary Distress None Existing Surface Clean? Yes Existing After Placement 2021 2022 Average rut depth, in. 0.029 0.208 0.211 Sand patch results, avg. diam., in. 19.30 9.67 11.78 12.50	Start MP	1278 from RR	1st Date Placed	8/27/20	Time Placed	8:45AM
Canopy Open-sunny Relative Humidity, % 84.0 2nd Date Placed n/a Time Placed n/a Air Temperature at Placement, F n/a Pavement Surface Temperature, F n/a Relative Humidity, % n/a Layout Straight and Flat Existing surface type Micro/slurry Existing Primary Distress Weathering Existing Secondary Distress None Existing Surface Clean? Yes Existing After Placement 2021 2022 Average rut depth, in. 0.029 0.208 0.211 Sand patch results, avg. diam., in. 19.30 9.67 11.78 12.50	End MP	1278+500	Air Temp	erature at Placeme	54.0	
2nd Date Placed n/a Time Placed n/a Air Temperature at Placement, F n/a Pavement Surface Temperature, F n/a Relative Humidity, % n/a Layout Straight and Flat Existing surface type Micro/slurry Existing Primary Distress Weathering Existing Secondary Distress None Existing Surface Clean? Yes Existing After Placement 2021 2022 Average rut depth, in. 0.029 0.208 0.211 Sand patch results, avg. diam., in. 19.30 9.67 11.78 12.50	Lane Direction	SB	Pavement	t Surface Temperati	71.0	
Air Temperature at Placement, F Pavement Surface Temperature, F N/a Relative Humidity, % N/a Layout Straight and Flat Existing surface type Micro/slurry Existing Primary Distress Weathering Existing Secondary Distress None Existing Surface Clean? Yes Existing After Placement None Existing After Placement None None Straight and Flat None None None None None None None None	Canopy	Open-sunny	Rel		84.0	
Pavement Surface Temperature, F Relative Humidity, % N/a Layout Straight and Flat Existing surface type Micro/slurry Existing Primary Distress Weathering Existing Secondary Distress None Existing Surface Clean? Yes Existing After Placement Average rut depth, in. 0.029 0.208 0.211 Sand patch results, avg. diam., in. 19.30 9.67 11.78 12.50			2nd Date Placed	n/a	Time Placed	n/a
Relative Humidity, % n/a Layout Straight and Flat Existing surface type Micro/slurry Existing Primary Distress Weathering Existing Secondary Distress None Existing Surface Clean? Yes Existing After Placement 2021 2022 Average rut depth, in. 0.029 0.208 0.211 Sand patch results, avg. diam., in. 19.30 9.67 11.78 12.50			Air Temp	erature at Placeme	nt, F	n/a
Layout Straight and Flat Existing surface type Micro/slurry Existing Primary Distress Weathering Existing Secondary Distress None Existing Surface Clean? Yes Existing After Placement 2021 2022 Average rut depth, in. 0.029 0.208 0.211 Sand patch results, avg. diam., in. 19.30 9.67 11.78 12.50			Pavemen	t Surface Temperati	ıre, F	n/a
Existing surface type Existing Primary Distress Existing Secondary Distress Existing Surface Clean? Existing Surface Clean? Existing After Placement O.202 Average rut depth, in. O.029 O.208 O.211 Sand patch results, avg. diam., in. O.029 O.208 O.211 O.208 O.211			Rel	ative Humidity, %		n/a
Existing Primary Distress Existing Secondary Distress None Existing Surface Clean? Existing Surface Clean? Existing After Placement O.202 Average rut depth, in. O.029 O.208 O.211 Sand patch results, avg. diam., in. 19.30 9.67 11.78 12.50	Layout		Straight and Fla	t		
Existing Secondary Distress Existing Surface Clean? Existing Surface Clean? Existing After Placement 2021 2022 Average rut depth, in. 0.029 0.208 0.211 Sand patch results, avg. diam., in. 19.30 9.67 11.78 12.50	Existing surface typ	е	Micro	/slurry		
Existing Surface Clean? Yes Existing After Placement 2021 2022 Average rut depth, in. 0.029 0.208 0.211 Sand patch results, avg. diam., in. 19.30 9.67 11.78 12.50	Existing Primary Distress		Weat	hering		
Existing After Placement 2021 2022 Average rut depth, in. 0.029 0.208 0.211 Sand patch results, avg. diam., in. 19.30 9.67 11.78 12.50	Existing Secondary Distress		No	one		
Average rut depth, in. 0.029 0.208 0.211 Sand patch results, avg. diam., in. 19.30 9.67 11.78 12.50	Existing Surface Clean?		Yes			
Sand patch results, avg. diam., in. 19.30 9.67 11.78 12.50			Existing	After Placement	2021	2022
	Average rut depth, i	n.	0.029		0.208	0.211
Mean texture depth, in. 0.042 0.167 0.113 0.101	Sand patch results, avg. diam., in.		19.30	9.67	11.78	12.50
	Mean texture depth	, in.	0.042	0.167	0.113	0.101
						_



	Existing	After Placement	2021	2022	2023			
PCI (ASTM D6433)	95	100.0	100	100				
Other notes	Berkamp M1A o	ontinuous unit - 1 power broom - 9 support units - Tom Litchy 3						
	248-9124 foren	nan - no visible mil	e post markings so	test section b	egins at 1278			
	south of railroa	d track - Colgan ND	- roadway has extre	emely low trat	ffic volumes -			
	3 miles from (Canada - existing pa	vement is approxin	nately 2-3 yea	rs old - very			
	minor rutting	and no cracking - T	ype 3 micro - 29 ft i	roadway plus	safety edge			
Weather Station	KNDCROSB4							
wunderground.com		Air Tempe	eratures, F					
1st Lift - Date:	8/27/20	High	ation, in.					
2 Days Prior to plac	ement	93.4	64.8	0.	00			
Day Prior to placem	ent	87.6	57.2	0.	00			
Day of placement		85.3	47.1	0.	01			
Day after placemen	t	76.5	48.7	0.	00			
2 Days after placem	nent	82.8	49.1	0.	00			



Existing Pa	avement N	leasurem	ents											
		Existing				20)21			20	22			
Rutting		Outside V	Vheelpath	Inside W	heelpath	Outside Wheelpath		Inside Wheelpath		Outside Wheelpath		Inside Wheelpath		
N	IP .	Dial Gaug	e Reading	Dial Gaug	e Reading	Dial Gau	ge Reading	Dial Gau	ge Reading	Dial Gau	e Reading Dial Gauge		e Reading	
1278 from RR		3	3	2	8	221 202		235		181				
1278 from RR	+50		9		0	2	239		L78	2	240		150	
1278 from RR	+100		0		0	2	24	2	206	239		222		
1278 from RR	+150	(0	6	55	2	21	1	l81	192		271		
1278 from RR	+200		8	8	36	1	.38	2	216	1	18	2:	24	
1278 from RR	+250	1	.5	14	49	2	11	1	L93	2	227	236		
1278 from RR	+300	(0	5	8	2	203	1	L89	1	189	226		
1278 from RR	+350		8	6	52	1	.79	2	281	127		227		
1278 from RR	+400		5	5	2	1	.59	2	238	1	184		256	
1278 from RR		(0	4	4	2	210	1	L80	203		221		
1278 from RR	+500	1	1	4	2	3	325	1	L84	301		174		
Average	Reading		5	5	3	2	212	2	204	205		2:	17	
Average Ru	t Depth, in.	0.0	005	0.0)53	0.	212	0.	204	0.	205	0.217		
Overall Avera	-	0.0)29			0.	208			0.	211			
Sand Patch			Date	8/26/20										
MP	Wheelpath	D1	D2	D3	D4	AVG.	MTD, in.							
	Outside	19.25	19.00	19.50	20.00	19.44	0.041							
	Inside	18.25	19.25	18.50	19.00	18.75	0.044							
	Outside	20.00	19.25	19.75	20.75	19.94	0.039							
	Inside	19.25	19.00	19.00	19.00	19.06	0.043							
					Average	19.30	0.042							

.....




Application	n Measure	ements						
Emulsion Temp	erature, F		160	Notes				
Emulsion S.G. at 60F		1.006						
Emulsion lbs./g	allon		8.400					
% Residue by D	istillation		62.8					
Correction Fact	or							
Mixture Applica	ation							
1st Lift	,	Bag		Roofing				
		w/micro	Roofing	w/micro	Area, sq.		Aggregate	Application
Sample	Bag wt., g	wt., g	Tare wt., g	wt., g	in.	Wheelpath	Rate in lbs./ sq. yd	
1	24.0	1930.0	500.0	581.0	253	Outside	22.4	
2	24.0	1722.0	500.0	566.0	253	Between	19.9	
3	24.0	1502.0	500.0	582.0	253	Inside	17.6	
						Average	20	0.0




Sand Patch After Application			Date	8/28/20			
MP	Wheelpath	D1	D2	D3	D4	AVG.	MTD, in.
1278 RR+100	Outside	9.50	9.50	9.25	9.75	9.50	0.172
1278 RR+100	In between	9.00	9.50	9.00	9.25	9.19	0.184
1278 RR+100	Inside	9.75	9.50	9.50	9.75	9.63	0.168
1278 RR+400	Outside	9.75	11.00	10.00	10.25	10.25	0.148
1278 RR+400	In between	8.50	10.25	9.50	9.50	9.44	0.174
1278 RR+400	Inside	9.50	10.50	10.00	10.00	10.00	0.155
					Average	9.67	0.167
Sand Patch Aft	er Application	- Year 1	Date	9/16/21			
MP	Wheelpath	D1	D2	D3	D4	AVG.	MTD, in.
1278 RR+100	Outside	12.50	13.75	12.50	12.75	12.88	0.094
1278 RR+100	In between	13.00	12.50	12.00	13.00	12.63	0.097
1278 RR+100	Inside	11.00	12.00	12.00	11.50	11.63	0.115
1278 RR+400	Outside	11.75	12.00	12.25	11.00	11.75	0.113
1278 RR+400	In between	11.50	10.50	10.50	11.00	10.88	0.131
1278 RR+400	Inside	11.00	11.25	11.00	10.50	10.94	0.130
					Average	11.78	0.113
Sand Patch Aft	er Application	- Year 2	Date	9/29/22			
MP	Wheelpath	D1	D2	D3	D4	AVG.	MTD, in.
1278 RR+100	Outside	12.50	13.50	13.00	12.75	12.94	0.093
1278 RR+100	In between	12.00	13.00	12.00	12.50	12.38	0.101
1278 RR+100	Inside	11.00	12.00	11.00	11.25	11.31	0.121
1278 RR+400	Outside	12.75	13.50	13.25	12.75	13.06	0.091
1278 RR+400	In between	13.75	13.50	13.00	14.50	13.69	0.083
1278 RR+400	Inside	12.00	12.00	11.25	11.25	11.63	0.115
					Average	12.50	0.101









Projects to date



- 21 projects placed to date
- 2019 1 project
 - NY
- 2020 12 projects
 - NY (2), NC, OH, VA (2), ND (2), SD, MD, KS, NV
- 2021 7 projects
 - DE, NC, AZ (3), MS
- 2022 1 project
 - ∘ CA



Projects Requirements



- Must be a good candidate road for the application type i.e. don't want a project putting micro on a severely cracked existing road
- Minimum of 1000 feet actual test section will be 500 feet but need 250 on either end
- Test section should be relatively flat and straight with good sight distance and consistent traffic (posted) speed
- Test section should not have side roads or other sources of traffic entering (businesses, manufacturing facilities, etc.)
- We will need traffic information as well as design/production info (chip seal, micro, slurry)
 past construction history of the section would also be helpful but not absolutely necessary
- It's not necessary but would ideal if one or more emulsions (residues) could be used on the same project to have multiple test sections i.e. CRS-2, CRS-2h, CRS-2p, RS-2, RS-2h, RS-2p – not all of these but just giving some examples for chip seal

Potential Projects



- Currently working on final plans for projects in AL, TN, GA, NY, New England
- Need projects in the northwest, southwest, and Midwest






In Loving Memory of Gregory M. Harder December 12, 2002 December 21, 2022

#LLGH



Questions?





Gregory A. Harder, P.E. Asphalt Institute Senior Regional Engineer 397 State Route 281 – Suite A Tully NY 13159

Office: 315-238-7000

Mobile: 315-807-7306

Fax: 315-238-7000

Email: gharder@asphaltinstitute.org